

Catch Basin Defects



Defect 1: This catch basin is higher than the surrounding asphalt.



Defect 2: A sinkhole has developed adjacent to the catch basin.



Defect 3: A collapsed pipe.



Defect 4: Frost heave has caused this basin to shift.